

October 14, 2016

Dear ESM Central High School Community:

I'd like to take this opportunity to inform you that we now have received all lead test data from samples of water that were taken from the high school prior to the Governor's September 6 signing of the law mandating such. Of 65 samples tested (see next pages), one site in the building currently exceeds the permissible limit (15 ppb) as defined by the new state law. That site and the district's actions taken/action plans are described below.

- Room D-16 prep sink (36 ppb) - actions taken; water shut off, removed and replaced copper supply pipe in basement, sign posted. Action planned; re-sample in October.

As of September 6, the law prescribes that additional outlets in the building be sampled and tested. Those samples will be drawn in October. Once received, the test results for those outlets will be made available on the district's website.

Thank you for your patience throughout this process.

Sincerely,

A handwritten signature in blue ink, appearing to read "John Young".

**John Young**  
Director of Facilities

**Central High School**

\* indicates that source reading exceeds 9/6/16 permissible level (15 ppb)

<b>Room</b>	<b>Lead</b>	<b>Actions Taken</b>	<b>Actions Planned</b>
Kitchen sink #2	2.6 ppb		
Kitchen sink-center	2.3 ppb		
Kitchen sink #1	3.8 ppb		
Kitchen soup spigot	4.5 ppb		
DF near lg. café L	<1 ppb		
Df near lg. café R	<1 ppb		
D wing DF left	<1 ppb		
D wing DF right	<1 ppb		
D11 sink	13 ppb		
D16 sink	36 ppb*	plumbing modification	re-test
D14 prep room sink	1.2 ppb		
D20 prep sink	5.5 ppb		
E wing DF nr lg caf L	13 ppb		
E wing DF nr lg caf R	11 ppb		
E11 sink South	<1 ppb		
E11 sink North	1.1 ppb		
E7 sink	<1 ppb		
E6 sink	<1 ppb		
DF in hall near E22 L	<1 ppb		
DF in hall near E22 R	<1 ppb		
E22 left	<1ppb		
E22 right	<1 ppb		
Library	2 ppb		
Nurse NS right	<1 ppb		
Nurse NS left	<1 ppb		
Staff Room KC	<1 ppb		
Office WC left 27-A	<1 ppb		
Office WC left 28-A	<1ppb		
DF near art room	8.8 ppb		
C wing teachers' bkr	1.5 ppb		
E20 sink #1	<1 ppb		
E20 sink #2	1.9 ppb		
E20 sink #3	<1 ppb		
E20 sink #4	<1 ppb		
C3	<1 ppb		
C3 prep sink #1	<1 ppb		
C3 prep sink #2	<1 ppb		
DF near G19	<1 ppb		
DF near G20 tall	<1 ppb		
DF near G20 short	<1 ppb		

G9 sink	<1 ppb
G13 (Teachers' Rm.)	1.1 ppb
DF near G14	<1 ppb
G14 sink	<1 ppb
Atrium Band area DF	<1 ppb
G3 Band Room DF	<1 ppb
Main Hallway DF L	1.7 ppb
DF near B13 R	1.5 ppb
DF near B13	4.8 ppb
B1 Faculty Room	<1 ppb
DF near B36	9.9 ppb
B2 Faculty Room	<1 ppb
DF near B43	<1 ppb
DF near B9 tall	<1 ppb
DF near B9 short	<1 ppb
DF near wgt rm tall	<1 ppb
DF near wgt rm shrt	<1 ppb
DF near AD tall	<1 ppb
DF near AD short	<1 ppb
DF near men's F7	5.9 ppb
Girls' PE Office sink	<1 ppb
Athl Trainer Off. sink	<1 ppb
Custodial Office	1.3 ppb
Concession Stand	3.4 ppb
Baseball Field	8.6 ppb