

Lake Street

Location Number	Description	Sample #	Sample Date	Results	Remediation
1	Gym Hall Water Fountain Left	LS-1	10/27/2020	<0.0010 mg/L	
2	Gym Hall Water Fountain Right	LS-2	10/27/2020	<0.0010 mg/L	
3	Boys Gang Bath Hand Sink Left	LS-3	10/27/2020	0.0028 mg/L	
4	Boys Gang Bath Hand Sink Center	LS-4	10/27/2020	0.0026 mg/L	
5	Boys Gang Bath Hand Sink Right	LS-5	10/27/2020	0.0032 mg/L	
6	Girls Gang Bath Hand Sink Left	LS-6	10/27/2020	0.0039 mg/L	
7	Girls Gang Bath Hand Sink Center	LS-7	10/27/2020	0.0040 mg/L	
8	Girls Gang Bath Hand Sink Right	LS-8	10/27/2020	0.0023 mg/L	
9	Boys Locker Water Fountain	LS-9	10/27/2020	Removed from service in 2016	
10	Boys Locker Bath Hand Sink Right	LS-10	10/27/2020	0.027 mg/L	Posted Non-Potable
11	Boys Locker Bath Hand Sink Left	LS-11	10/27/2020	0.029 mg/L	Posted Non-Potable
12	Girls Locker Water Fountain	LS-12	10/27/2020	Removed from service in 2016	
13	Girls Locker Bath Hand Sink Left	LS-13	10/27/2020	0.013 mg/L	
14	Girls Locker Bath Hand Sink Right	LS-14	10/27/2020	Removed from service in 2016	
15	Girls Locker Custodial Sink	LS-15	10/27/2020	0.31 mg/L	Posted Non-Potable
16	Girls PE Office Hand Sink	LS-16	10/27/2020	0.010 mg/L	
17	Boys PE Office Hand Sink	LS-17	10/27/2020	0.0087 mg/L	
18	Room 129 Hand Sink Left	LS-18	10/27/2020	0.0011 mg/L	
19	Room 129 Hand Sink Right	LS-19	10/27/2020	<0.0010 mg/L	
20	Room 129 Water Fountain	LS-20	10/27/2020	0.0045 mg/L	
21	Room 125 Hand Sink Right	LS-21	10/27/2020	0.0021 mg/L	
22	Room 125 Hand Sink Left	LS-22	10/27/2020	<0.0010 mg/L	
23	Room 125 Water Fountain	LS-23	10/27/2020	0.016 mg/L	Shut off and Remove from Service
24	Room 123 Hand Sink Left	LS-24	10/27/2020	0.0014 mg/L	
25	Room 123 Hand Sink Right	LS-25	10/27/2020	0.0027 mg/L	
26	Room 123 Water Fountain	LS-26	10/27/2020	<0.0010 mg/L	
27	Room 119 Hand Sink Right	LS-27	10/27/2020	0.0065 mg/L	
28	Room 119 Hand Sink Left	LS-28	10/27/2020	<0.0010 mg/L	
29	Room 119 Water Fountain	LS-29	10/27/2020	<0.0010 mg/L	
30	Room 115 Hand Sink	LS-30	10/27/2020	<0.0010 mg/L	
31	Room 115 Water Fountain	LS-31	10/27/2020	<0.0010 mg/L	
32	Room 112/113 Bath Hand Sink	LS-32	10/27/2020	<0.0010 mg/L	
33	Room 107 Hand Sink	LS-33	10/27/2020	0.0034 mg/L	
34	Room 107 Water Fountain	LS-34	10/27/2020	Not functioning	Shut off and Remove from Service
35	Room 109 Hand Sink	LS-35	10/27/2020	0.0013 mg/L	
36	Room 109 Water Fountain	LS-36	10/27/2020	Not functioning	Shut off and Remove from Service
37	Library Office 137 Hand Sink	LS-37	10/27/2020	0.032 mg/L	Posted Non-Potable, Replace fixture/supply lines/shutoff, Retest
38	1st Floor Custodial Sink	LS-38	10/27/2020	0.0062 mg/L	
39	Faculty Room Hand Sink	LS-39	10/27/2020	0.0037 mg/L	
40	Faculty Room Bath Hand Sink	LS-40	10/27/2020	0.0021 mg/L	
41	Main Office Hallway Water Fountain	LS-41	10/27/2020	0.0034 mg/L	
42	Room 105 Hand Sink	LS-42	10/27/2020	<0.0010 mg/L	
43	Room 105 Water Fountain	LS-43	10/27/2020	<0.0010 mg/L	
44	Room 103 Hand Sink	LS-44	10/27/2020	<0.0010 mg/L	
45	Room 103 Water Fountain	LS-45	10/27/2020	<0.0010 mg/L	
46	Nurses Office Bath Hand Sink	LS-46	10/27/2020	0.017 mg/L	Posted Non-Potable, Replace fixture/supply lines/shutoff, Retest
47	Nurses Office Hand Sink	LS-47	10/27/2020	0.0083 mg/L	
48	Main Office Hand Sink	LS-48	10/27/2020	0.0010 mg/L	
49	Art Room 101 Right Hand Sink	LS-49	10/27/2020	Not functioning	Posted Non-Potable, Repair Fixture and Test
50	Art Room 101 Left Hand Sink	LS-50	10/27/2020	Not functioning	Posted Non-Potable, Repair Fixture and Test
51	Main Office Bath Hand Sink	LS-51	10/27/2020	0.0022 mg/L	
52	Room 133 Hand Sink	LS-52	10/27/2020	0.0023 mg/L	
53	Room 133 Water Fountain	LS-53	10/27/2020	0.0052 mg/L	
54	Room 135 Hand Sink	LS-54	10/27/2020	0.0018 mg/L	
55	Room 135 Water Fountain	LS-55	10/27/2020	<0.0010 mg/L	
56	Room 215 Water Fountain	LS-56	10/27/2020	<0.0010 mg/L	
57	Room 215 Hand Sink	LS-57	10/27/2020	<0.0010 mg/L	
58	Room 218 Hand Sink	LS-58	10/27/2020	<0.0010 mg/L	

Retest Sample # Retest Date Retest Results

Lake Street

59	Room 218 Water Fountain	LS-59	10/27/2020	<0.0010 mg/L	
60	Room 213 Water Fountain	LS-60	10/27/2020	<0.0010 mg/L	
61	Room 213 Hand Sink	LS-61	10/27/2020	<0.0010 mg/L	
62	Room 207 Hand Sink	LS-62	10/27/2020	<0.0010 mg/L	
63	Room 207 Water Fountain	LS-63	10/27/2020	Not functioning	Shut off and Remove from Service
64	Room 201 Water Fountain	LS-64	10/27/2020	<0.0010 mg/L	
65	Room 201 Hand Sink	LS-65	10/27/2020	<0.0010 mg/L	
66	Room 203 Hand Sink	LS-66	10/27/2020	<0.0010 mg/L	
67	Room 203 Water Fountain	LS-67	10/27/2020	<0.0010 mg/L	
68	Room 205 Hand Sink	LS-68	10/27/2020	<0.0010 mg/L	
69	Room 205 Water Fountain	LS-69	10/27/2020	<0.0010 mg/L	
70	2nd Floor Custodial Sink	LS-70	10/27/2020	0.012 mg/L	
71	Room 211 Water Fountain	LS-71	10/27/2020	<0.0010 mg/L	
72	Room 211 Hand Sink	LS-72	10/27/2020	<0.0010 mg/L	
73	Basement Bath Hand Sink	LS-73	10/27/2020	0.020 mg/L	Posted Non-Potable
74	Cafeteria Water Fountain	LS-74	10/27/2020	<0.0010 mg/L	
75	Kitchen Sink Left West Wall	LS-75	10/27/2020	0.026 mg/L	Temporarily removed from service, Replace fixture/supply lines/shutoff, Retest
76	Kitchen Sink Center West Wall	LS-76	10/27/2020	0.018 mg/L	Temporarily removed from service, Replace fixture/supply lines/shutoff, Retest
77	Kitchen Sink Right West Wall	LS-77	10/27/2020	0.044 mg/L	Temporarily removed from service, Replace fixture/supply lines/shutoff, Retest
78	Basement Custodial Sink	LS-78	10/27/2020	0.0032 mg/L	
79	Basement Hallway Water Fountain	LS-79	10/27/2020	Not functioning	Posted Non-Potable, Repair Fixture and Test
80	Room 102 Bath Sink	LS-80	10/27/2020	0.0014 mg/L	
81	ESM Prep Sink Left	LS-81			
82	ESM Prep Sink Center	LS-82			
83	ESM Prep Sink Right	LS-83			
84	ESM Hand Sink	LS-84			