Lead in Drinking Water Test Results					
St Matthe	w's School		ppb	Δ	ction(s), if needed
	Location		pps	+	etion(3), ii needed
· ·		 ' Sink	8.85	:	
	1st Fl Boys' Sink 1st Fl Boys' Sink		2.32		
	1st Fl Boys' Sink		3.42		
	1st Fl Boys' Sink		4.24		
	1st Fl Girls' Sink		3.32		
	1st Fl Girls' Sink		2.9		
	1st Fl DF		14.7		
	2nd Fl Boys' Sink		3.77	+	
	2nd Fl Boys' Sink		3.66		
	2nd Fl Boys' Sink		4.26		
	2nd Fl Boys' Sink		5.95		
	2nd Fl Girls' Sink		7.26		
	2nd Fl Girls' Sink		10.8		
	2nd Fl DF	JIIIK	30.2		hut down - 12/9/2020
	2nd Fl Staff Bath		25		osted non-potable previously
	Basement Staff Bath		<1.		osted non-potable previously
	Bsmt Resource Sink		3.99		
	Basement DF		<1.		
	Kitchen Sink		7.44		
	Kitchen DW Sink		14.2	+	
	Music Room		<1.		
	1st Fl Rm 145 Sink		4.85		
	Gym Boys' Rm Sink		4.97		
	Gym Boys' Rm Sink		8.29		
	Gym Boys' Rm Sink		6.35		
	Gym Girls' Rm Sink		18.1		hut down 12/9/2020
28	Gym Girls' Rm Sink		7.87		
	Gym Girls' Rm Sink		3.33	+	
	Gym Girls' Rm Sink		13.1		
	1st Fl Staff Bath sink		10.9		
	PE Office Sink		7.3		
	1st FI DF		<1.		
	Isolation Room		16.2		osted non-potable previously
	Kitchen Sink		2.36		· · · · · · · · · · · · · · · · · · ·