

**Park Hill Pre-K**

<b>Room</b>	<b>Lead</b>	<b>Actions Taken</b>	<b>Action Plan</b>
Kitchen sink	15 ppb	installed in-line filter	
Cafeteria DF left	1.3 ppb		
Cafeteria DF right	9.5 ppb		
305 sink	8.4 ppb		
Nurse's front sink	4.2 ppb		
Nurse's back sink	9.3 ppb		
Basement DF	<1 ppb		
6 sink	8.1 ppb		
Basement sink	5.2 ppb		
104 sink	<1 ppb		
1st Floor Hallway DF	2.1 ppb		
103A sink	1.7 ppb		
208 sink	3.4 ppb		
2nd Floor DF	5.1 ppb		
2nd fl. womens' R	3.9 ppb		
<b>301 DF</b>	<b>39 ppb*</b>	<b>water shut off</b>	<b>permanently decommissioned</b>
<b>301 sink</b>	<b>3.6 ppb</b>		
<b>301 bathroom</b>	<b>12 ppb</b>		
<b>302 DF</b>	<b>22 ppb*</b>	<b>water shut off</b>	<b>permanently decommissioned</b>
<b>302 sink</b>	<b>2.6 ppb</b>		
<b>302 bathroom</b>	<b>6.9 ppb</b>		
<b>303 DF</b>	<b>15 ppb</b>	<b>water shut off</b>	<b>permanently decommissioned</b>
<b>303 sink</b>	<b>6.1 ppb</b>		
<b>303 bathroom</b>	<b>6 ppb</b>		
<b>304 bathroom</b>	<b>7.7 ppb</b>		
<b>305 bathroom</b>	<b>5 ppb</b>		
<b>306 DF</b>	<b>83 ppb*</b>	<b>water shut off</b>	<b>permanently decommissioned</b>
<b>306 sink</b>	<b>5.1 ppb</b>		
<b>306 bathroom</b>	<b>5.2 ppb</b>		
<b>307 sink</b>	<b>7.5 ppb</b>		
<b>307 bathroom</b>	<b>6.8 ppb</b>		
<b>308 DF</b>	<b>67 ppb*</b>	<b>water shut off</b>	<b>permanently decommissioned</b>
<b>308 sink</b>	<b>9.4 ppb</b>		
<b>308 bathroom</b>	<b>5.4 ppb</b>		
<b>309 DF</b>	<b>34 ppb*</b>	<b>water shut off</b>	<b>permanently decommissioned</b>
<b>309 sink</b>	<b>4.4 ppb</b>		
<b>309 bathroom</b>	<b>8.9 ppb</b>		
<b>1st fl. Boys' bath #1</b>	<b>1.8 ppb</b>		
<b>1st fl. Boys' bath #2</b>	<b>1.3 ppb</b>		
<b>103A bathroom</b>	<b>6.1 ppb</b>		
<b>1st fl. Girls' bath #1</b>	<b>4.5 ppb</b>		
<b>1st fl. Girls' bath #2</b>	<b>5.4 ppb</b>		
<b>2<sup>nd</sup> fl. Girls' bath #1</b>	<b>&lt;1 ppb</b>		

\* indicates that source reading exceeds 9/6/16 permissible level (15 ppb)

**Results received on 10/13/2016 are listed in bold.**